

HABS
SC
10-EDIL
2-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

William Seabrook House
County road 768, near State Route 174
Edisto Island
Charleston County
South Carolina

HABS No. SC-124

Addendum to:

William Seabrook House
Edisto Island
Charleston County
South Carolina

Photo SC-124-1 was previously transmitted to the Library of Congress. The photos below were taken in November 1978 for the South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

- SC-124-2 SOUTH (FRONT) ELEVATION
- SC-124-3 SOUTHEAST SIDE
- SC-124-4 SOUTHWEST SIDE
- SC-124-5 NORTH (REAR) ELEVATION. Enclosed porches are ca. 1920.
- SC-124-6 EAST SIDE. Projection houses elevator.
- SC-124-7 NORTHWEST SIDE
- SC-124-8 SOUTH SIDE, FIRST FLOOR PORTICO: IRON RAILING CIPHER OF BUILDER (W.S.)
- SC-124-9 SOUTH SIDE, FIRST FLOOR: MAIN ENTRY
- SC-124-10 SOUTH SIDE, SECOND FLOOR: PORTICO ENTRY
- SC-124-11 SOUTH SIDE PORTICO: FIRST FLOOR CORNICE DETAIL
- SC-124-12 SOUTH SIDE PORTICO: PEDIMENT DETAIL
- SC-124-13 SOUTH SIDE: DORMER AND CORNICE DETAIL
- SC-124-14 EAST SIDE GABLE: WINDOW DETAIL
 Window in west side gable same
- SC-124-15 EAST SIDE: SECOND FLOOR CORNICE DETAIL. Note handling of
 ovolo crown molding of raking cornice at flare of roof line

(continued on page 2)

WILLIAM SEABROOK HOUSE
Index To Photographs
HABS No. SC-124 (page 2)

- SC-124-16 FIRST FLOOR HALL: LOOKING NORTH TO STAIRHALL. NOTE
UNIQUE DOUBLE STAIRWAY
- SC-124-17 FIRST FLOOR HALL: LOOKING SOUTH TO ENTRY
- SC-124-18 FIRST FLOOR HALL: DETAIL VIEW OF STAIRWAY. NOTE PANELED
UNDERSIDE, SCROLLWORK AND WAINSCOT. ALSO NOTE
DOORS
- SC-124-19 FIRST FLOOR HALL: DOOR TO SOUTHWEST ROOM.
Door to southeast room same
- SC-124-20 FIRST FLOOR HALL: CORNICE DETAIL
- SC-124-21 FIRST FLOOR, SOUTHEAST ROOM, NORTH WALL.
Corner cabinet is new. Elevator door is at right; originally a window.
- SC-124-22 FIRST FLOOR, SOUTHEAST ROOM, NORTH WALL: MANTLE DETAIL
- SC-124-23 FIRST FLOOR, SOUTHEAST ROOM: CORNICE DETAIL
- SC-124-24 FIRST FLOOR, SOUTHEAST AND SOUTHWEST ROOMS: TYPICAL WINDOW
SPANDREL AND WAINSCOT
- SC-124-25 SECOND FLOOR HALL: LOOKING SOUTH FROM STAIR LANDING. NOTE
PORTICO DOOR IN THE BACKGROUND (see also SC-497-9)
- SC-124-26 SECOND FLOOR STAIRHALL LOOKING NORTH. NOTE ELLIPTICAL CEILING
AND WAINSCOT OF DOUBLE STAIRWAY
- SC-124-27 SECOND FLOOR, SOUTHEAST ROOM, NORTH WALL. Door at left shows
typical hall side of all second floor doors
- SC-124-28 SECOND FLOOR, SOUTHEAST ROOM, NORTH WALL: MANTLE DETAIL.
Typical for second floor rooms and northwest room in first floor.
- SC-124-29 SECOND FLOOR, SOUTHEAST AND SOUTHWEST ROOMS: CORNICE DETAIL
- SC-124-30 SECOND FLOOR: TYPICAL WINDOW SPANDREL, WAINSCOT CAP AND
MARBLEIZED BASE